



Snug tight bolt and nut
in splice plate prior to
welding
Weld 2 opposite faces
on 2 sides of nut